

**No.169 WATER PROOF TESTER**



JIS-K6404-7, L1092, ISO-811

**FEATURE**

This tester is used for testing the water proofing of rubber cloth.

**SPECIFICATIONS**

- Specimen** 150x150mm
- Clamp** Inside  $\phi$ 100mm
- Pressure gauge** Max. 0.3MPa (Unit 0.002MPa) or Max. 0.6MPa (Unit 0.005MPa)
- Grating**  $\phi$ 140mm, Spot  $\phi$ 3mm ··· 45pcs
- Dimensions·Weight (Approx.)** W420xD500xH700mm·45kg

**No.197 FLEXOMETER**

**No.197-LFR FLEXOMETER WITH LOW TEMP. OVEN**



No.197

JIS-K6542, K6545

**FEATURE**

This instrument is used for testing the flexibility of leather of shoe and thin leather.

**SPECIFICATIONS**

Model	No.197	No.197-LFR
Hangings	12hangings	
Soecimen	70x45mm	
Fleing angle	22.5°	
Flecing speed	100±5times/min	
Counter	6digits preset counter	
Temperature range	—	-30~70°C (Refrigerator)
Power source	AC220V 1-phase 10A 50/60Hz	AC220V 3-phases 30A 50/60Hz
Dimensions·Weight (Approx.)	[Main body] W620x D500xH280mm·60kg [Control box] W300x D220xH300mm·7kg	W1,130xD830x H1,080mm·300kg



No.197-LFR